General Environmental Incident Summary

Incident: 3218 Date/Time Notice: 2/28/2014 DEM Incident No:

Responsible Party: Randy Ashment

Date Incident:2/27/2014Time Incident:19:57Duration:County:McKenzieTwp:149Rng:91Sec:9Qtr:Lat:47.74867Long:-103.28130Method:Interpolation from map

Location Description: 12621 23rd a St NW, Watford City, ND

Submitted By: Darren Anderson **Affiliation:**

Address: P.O. Box 458

City: Belfield State: ND Zip:

Received By:
Contact Person:

P.O. Box 458 Belfield, ND 58622

Distance Nearest Occupied Building:

Type of Incident: Tank Overflow

Description of Released Contaminant: SW

Volume Spilled: 1.00 barrels Ag Related: No EPA Extremely Hazardous Substance: Unknown Reported to NRC: No

Cause of Incident:

MBI, driver Randy Ashment trk #606/587 was loading from a storage tank in the Watford City yard and switched to his trailer. When he got 50 BBLs on, SW started spilling out of his overfill pipe. Before he could shut down a BBL of SW spilled on the ground. Randy conducted clean-up. Kiowa Jones (FSR) investigated.

Risk Evaluation:

of Fatalities: # of Injuries: Affected Medium:

Potential Environmental Impacts:

Action Taken or Planned:

The driver cleaned up the spill

Wastes Disposal Location: The contaminated material was taken to the Jellesed SWD

Agencies Involved:

Friday, January 27, 2017 Page 1 of 2

Updates

Date: 2/28/2014 Status: Reviewed - No Action Required Author: Roberts, Kris

Updated Volume:

Notes:

Telephone call this date to reporting party. Release was cleaned up and taken to disposal immediately upon discovery. Location is within company yard south of Watford City. No inspection required in this instance.

Friday, January 27, 2017 Page 2 of 2